

**ERRATA SHEET FOR
ANSI/ASHRAE STANDARD 79-2015
Method of Test for Fan-Coil Units**

February 29, 2016

The corrections listed in this errata sheet apply to ANSI/ASHRAE Standard 79-2015.
The first printing is identified on the outside back cover of the standard as “Product code:
86211 10/15”

<u>Page</u>	<u>Erratum</u>
--------------------	-----------------------

- | | |
|----------|--|
| 6 | 5.1.2.8 Airflow Measurements. In the first sentence of Section 5.1.2.8 change “Methods 1 and 2” to “Methods a and b”. |
|----------|--|