

**ERRATA SHEET FOR  
ANSI/ASHRAE/IES STANDARD 100-2018  
Energy Efficiency in Existing Buildings**

**June 26, 2024**

The corrections listed in this errata sheet apply to ANSI/ASHRAE/IES Standard 100-2018.  
The first printing is identified on the outside back cover as “Product code: 86299 3/18”.

|                    |                       |
|--------------------|-----------------------|
| <b><u>Page</u></b> | <b><u>Erratum</u></b> |
|--------------------|-----------------------|

|           |                                                      |
|-----------|------------------------------------------------------|
| <b>69</b> | <b>E2.2.5.</b> Revise Section E2.2.5 as shown below. |
|-----------|------------------------------------------------------|

*(Note: Additions are shown in underline and deletions are shown in ~~striketrough~~.)*

**E2.2.5** Use high-efficiency fans and pumps; replace or trim impellers of existing ~~fans~~pumps if they have excessive capacity relative to peak demand.